HOISTING AND LIFTING TOOL



REPAIR, REBUILD, AND CERTIFY

Rod, Tubing, Casing and Drilling Tools

API RP 8B Hoisting Tool Repair Process

Prices are for base inspections following API Recommended procedures, including:

- Visual inspection and tear-down
- Mag particle test
- Reassembly and function test
- Load test
- Mag particle 24 hours after load test
- · Reassembly, grease and paint

Repairs are performed in accordance with OEM specifications.

Did you know?

HSC can tailor our repair program to your standard procedures. Different paint color...Special process...Custom reporting requirement? We are a customer focused, service oriented company. We will do everything possible to ensure that our customers are able to accomplish their mission.

Tubing Spider*



Repair includes: sand blast, paint, MPI, load test, new cylinder, crank arms, lifting arms, taper pins, retainers, bushings, spacers, bolts, and nuts. Slip bodies are extra if needed.

< Tubing spider after sandblast

Tubing Spider Major*

Includes same parts as a regular certification plus **welding and machining of the bowl (per customer request) if bowl has excessive wear.





Rod Elevator



Repair includes: sandblast, paint, MPI, load test, roll pins, retainers and springs.

< Condition on arrival

New Norris rod elevators >



Tubing Elevator



Repair includes: sandblast, paint, MPI, load test, new pins, springs and grease fittings.

< Westco tubing elevator

Tubing Elevator Major

Includes same parts as regular certification plus welding and machining of the bore.

Rod Hook



Repair includes: sandblast, paint, MPI, load test, roll pins, latch spring and grease fitting.

< Re-certified rod hook with custom paint

Rod Clevis

Repair includes: sandblast, paint, MPI, load test, cotter pins.





Tubing Link

Repair includes: MPI, pull test, paint.

Did you know?

HSC offers both API RP 8B Category 3 & 4 Service. HSC can train your staff on preventative maintenance, inspection, and more. Our world class technicians will provide a comprehensive program to keep you in compliance.

All major parts and major repairs are additional charges.

^{*} Tubing Spider does not fall under API RP 8B - Service provided is equal to API service.

^{**}Per customer requirements. HSC procedures are available for review

Services

- Sales, service and delivery from the largest stock of well service specialty products in the United States
- Hoisting and lifting tool inspection, repair and recertification
- Traveling block inspection repair and recertification
- Power tong repair
- Custom wire rope and chain slings
- Wire rope spooling and splicing
- Hoisting tool, block, and sling pull/load testing
- Portable pull testing
- Weight indicator repair
- High pressure iron (HPI) sales and recertification

- Depthometer repair
- Air, transfer, hydraulic hose fabrication and repair
- Machine shop services
 - Custom fabrication and machining
 - Shearing and braking
 - Rolling services
 - Tool reworking
- Oil saver repair
- Brake band service and re-lining
- Shear relief, air valve, and ball valve repair, rebuilding and testing
- Field and shop welding
- Overhead lifting safety training

